

Read/Write for MacOS 10.12 is very slow, how do I or how can I improve the performance in these steps?

Model:

ARC Series B and C Adapters (10G-PCIE2-8B2-2S and 10G-PCIE2-8C-2S)

Software:

Myri10G Drivers

Operating System:

MacOS 10.12 (Sierra)

Information:

After installing/upgrading my Mac to MacOS version 10.12 (Sierra) on my thunderbolt. I noticed a significant drop off in the read/write capabilities of my system. Does a fix or work around this issue exist to improve my systems performance?

We recommend the following script be used: `printf "[default]\nsigning_required=no\n" | sudo tee /etc/nsmb.conf >/dev/null`

Once the script has been executed, Reboot the machine and verify the adapter is functioning properly.

Draft	Date	Change
1	12/2/16	Initial Draft

